THE CONNECTING BETWEEN TOYOTA VEHICLES ARE NOT OBD-II AND EFI SCAN

A. LOCATION OF CONNECTOR & ECU







B. CONNECTION IN THE DIAGNOSE ENGINE SYSTEM

1. Case of DLC1


1.1. Case of W pin is available on the connector




1.2. Case of W pin is not available on the connector



2. Case of both DLC1 & DLC2




3. Case of DLC3 (16 pins look like OBD-II but pin 13 is available)



C. CONNECTION IN THE DIAGNOSE ABS SYSTEM

1. Case of DLC1

→ Note, you must remove jumper of Wa-Wb



2. Case of DLC3

